

Driver Installation Under Windows 2000

1. **Step 1:** Plug in the USB type A receptacle of the cable to the USB connector of your computer.

Step 2: Place the enclosed CD Driver into the CD ROM.

Step 3: Click “next” at the welcome screen. See Figure 1



Figure 1

2. The “Found New Hardware Wizard” will install the driver automatically.

Click “next” button to search for a suitable driver

(default and recommended). See Figure 2



Figure 2

3. Choose “ CD-ROM “ drives and click “next”. See Figure 3



Figure 3

4. Click “next” to install the driver. See Figure 4



Figure 4

5. Click “ **Finish** ” to close the Wizard. See Figure 5



Figure 5

6. Double click “My Computer” →”System Properties”→”Device Manager” to make sure the device you install is correctly displayed. See Figure 6




Figure 6